Case Study

Project: Date: Designer: Installer: Location: Auckland Hill, Area 3 Slope Remediation May 2020 Coffey Ground Stabilisation Systems (GSS) Gladstone, Queensland



Slope Stabilisation – Macmat R

Coffey Services Australia Pty Ltd (Coffey) was engaged by Gladstone Regional Council to undertake a general slope stability assessment and a detailed design of remedial measures for one of the slopes (namely Ärea 3") at Auckland Hill in Gladstone, Queensland. Situated at the entrance of the harbour, Auckland Hill is a Council reserve predominantly utilised as parkland.

In early 2008 significant rainfall in the Gladstone region preceded a landslip on the eastern side of Auckland Hill, north of the Gladstone Ports Corporation (GPC) owned workshop and directly adjacent to Bishops Drive. This slip is encompassed within Area 3. The area of instability is still mostly bare, or with sparse vegetation, suggesting that the instability is still active, potentially in the form of unravelling and slumping.

The scarp associated with the existing instability is a steep cliff face (approximately 70°) that is ~45 m wide, has a maximum height of ~20 m in the northern section, tapering to ~2 m height in the southern section. The exposed rock is highly weathered mudstone/ arenite with moderately spaced sub-vertical defects. These are cross cut by low angle joints, forming blocks that have become loose and fallen from the slope. The joints are generally tight (rock-rock contact) to slightly open, rough, and weathered to form a distinct orange iron oxide or silt infill.

Some scrub vegetation has become established on the older debris material, and around the cliff exposure. The slope angle on the lower slope below the steep cliff face is approximately 25 - 40°.

The landslip has caused some tension cracking in the road pavement, which was also evident in a previous investigation carried out by Coffey following the 2008 slope instability event. Observations however indicate that these cracks have not lengthened or widened significantly since the 2008 event.

Due to the significant difficult access requirements a specialist installer (GSS) was engaged by GRC to carry out the works to the highest quality.



The Slope At Area 3 Prior To Remediation



GSS Drilling Anchors On The Slope

Case Study



The Anchored Macmat R On The Lower Slope And Shotcrete On The Upper Slope



The Completed Project Prior To Hydroseeding

The remediation of Area 3 was carried out by Ground Stabilisation Systems with a combination of the following:

• The localised regrading of the slope and removal of loose rock blocks, cobbles, and boulders on the slope

• The installation of shotcrete at the upper part of the slope and Maccaferri Macmat R (a reinforced geomat made from a polymeric three-dimensional matrix extruded onto a double twisted steel wire woven mesh) at the lower part of the slope in order to retain unstable cobbles, boulders and rock wedges

• The installation of soil nails to improve global and local slope stability

• The construction of a spoon drain at the crest of the exposure to capture and divert surface water flow away from the exposure face

• The construction of sub-horizontal drains to capture and divert groundwater away from the exposure face

• Application of hydromulch to the Macmat R to promote vegetation establishment in accordance with the CMDG Lanscaping C273 Specification (Table C273.06.1)

www.geofabrics.com.au

MELBOURNE (03) 8586 9111 Fax: (03) 8586 9186
 SYDNEY
 I

 (02) 9821 3277
 (

 Fax: (02) 9821 3670
 Fax

 NEWCASTLE
 COFFS HARBOUR

 (02) 4950 5845
 (02) 6658 4598

 Fax: (02) 4950 5895
 Fax: (02) 6658 4598

 BOUR
 PERTH

 4598
 (08) 9249 5411

 4598
 Fax: (08) 9249 5447

ADELAIDE (08) 8177 2055 Fax: (08) 8177 2044

HOBART (03) 6273 0511 Fax: (03) 6273 0686
 BRISBANE
 TOWNSVILLE

 (07) 3279 1588
 (07) 4774 8222

 Fax: (07) 3279 1589
 Fax: (07) 4774 8655

LLE BUN 222 (07) 4 8655 Fax (07

BUNDABERG (07) 4155 9968 (07) 5594 8600 Fax: (07) 4155 9968 Fax: (07) 5563 3727 DARWIN (08) 8984 1600 Fax: (08) 8984 1614